

# **Errata to IEEE Standard Practice and Requirements for Semiconductor Power Rectifier Transformers**

Sponsor

**Transformer Committee**

of the

**IEEE Power Engineering Society**

*Correction Sheet*

**Issued 27 January 2006**

Copyright © 2006 by the Institute of Electrical and Electronics Engineers, Inc. All rights reserved.  
Published 2006. Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.

**Page 29, Figure 6—Rectifier circuits (double-way circuits) (*Continued*), should be renumbered as follows:**

Figure 5—Rectifier circuits (double-way circuits) (*Continued*)

**Page 30, Figure 7—Rectifier circuits (multiple circuits, single-way), should be renumbered as follows:**

Figure 6—Rectifier circuits (multiple circuits, single-way)

**Page 31, Figure 8—Rectifier circuits (multiple circuits, single-way) (*Continued*), should be renumbered as follows:**

Figure 6—Rectifier circuits (multiple circuits, single-way) (*Continued*)

**Page 32, Figure 9—Rectifier circuits (miscellaneous circuits), should be renumbered as follows:**

Figure 7—Rectifier circuits (miscellaneous circuits)

**Page 49, Table A.11—2700 kVA (fundamental), dry-type transformer, 150 rise, aluminum windings, should be renumbered as follows:**

Table A.1—2700 kVA (fundamental), dry-type transformer, 150 rise, aluminum windings

**Page 50, Table A.12—Load current harmonic spectrum for two-winding transformer, should be renumbered as follows:**

Table A.2—Load current harmonic spectrum for two-winding transformer

**Page 50, Table A.13—Harmonic loss factors for two-winding transformer, should be renumbered as follows:**

Table A.3—Harmonic loss factors for two-winding transformer