

**IEEE Std 80™-2000**(Revision of  
IEEE Std 80-1986)

# Errata to IEEE Guide for Safety in AC Substation Grounding

Sponsor

**Substations Committee**

of the

**IEEE Power Engineering Society***Correction Sheet***Issued 21 February 2007**

Copyright © 2007 by the Institute of Electrical and Electronics Engineers, Inc. All rights reserved.  
Published 2007. Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified. This information has been incorporated into the second printing of IEEE Std 80-2000.

Page 24, Figure 12—Basic shock situations, should be replaced with the following figure:




Figure 12—Basic shock situations