

**IEEE Std C37.102™-2006**  
(Revision of  
IEEE Std C37.102-1995)

# Errata to IEEE Guide for AC Generator Protection

Copyright 2017 by The Institute of Electrical and Electronics Engineers, Inc.  
All rights reserved. Published 2017.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.

Sponsor  
Power System Relaying Committee  
of the  
IEEE Power and Energy Society

*Correction Sheet*  
**Issued 5 April 2017**

Correction sheet to IEEE Std C37.102™-2006

*The designation on each page is incorrect as IEEE Std C37.102-1006. Correct the designation in the headers on each page of the document as shown:*

IEEE Std C37.102-2006

*The text in 4.4.1.5 is incorrect. Correct the text to read as follows:*

The relay set points are in ohms typically with a 20 k $\Omega$  alarm and 5 k $\Omega$  trip or critical alarm.