

Errata to IEEE Standard Test Procedure for Impulse Voltage Tests on Insulated Conductors

Sponsor

Insulated Conductors Committee

of the

IEEE Power Engineering Society

Correction Sheet

Issued 11 August 2009

Copyright © 2009 by the Institute of Electrical and Electronics Engineers, Inc. All rights reserved. Published 2009.
Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified. Contents of this correction sheet have been incorporated into the second printing of IEEE Std 82-2002.

Page 5, replace Figure 1—Impulse BIL test, with the following:




Figure 1—Impulse BIL test