

IEEE Std C37.90.1™-2002

(Revision of
IEEE Std C37.90.1™-1989)

Correction to: IEEE Standard for Surge Withstand Capability (SWC) Tests for Relays and Relay Systems Associated with Electric Power Apparatus

Sponsor

Power System Relaying Committee
of the
Power Engineering Society

Correction Sheet Issued

28 June 2004

Figure 1 is not consistent with subclause 4.1a in respect to the rate at which the waveform envelope decays to 50% of peak value. Figure 1 should indicate a decay within 3-6 μs , not 4-6 μs . The corrected figure follows.




Figure 1—Oscillatory test waveform