

# Errata to IEEE Recommended Practice for Testing Switchgear Rated Up to 52 kV for Internal Arcing Faults

Developed by the  
**Switchgear Committee**  
of the  
**IEEE Power and Energy Society**

*Correction Sheet*  
**28 November 2025**

Copyright © 2025 by The Institute of Electrical and Electronics Engineers, Inc.  
All rights reserved. Published 2025. Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed, or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.

*In subclause 5.5, please replace Figure 6 with the following figure:*

