

IEEE Std C57.19.00™-2004

(Revision of
IEEE Std C57.19.00-1991)

Errata to IEEE Standard General Requirements and Test Procedure for Power Apparatus Bushings

Sponsor

IEEE Transformers Committee

of the

IEEE Power Engineering Society

Correction Sheet

Issued 1 April 2010

Copyright © 2010 by the Institute of Electrical and Electronics Engineers, Inc. All rights reserved. Published 2010.
Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.

Page 16, the dashed list in 7.4.3 should be changed to a lettered list as shown below:

The following test procedures shall be used:

- a) Measure RIV or apparent charge at 1.5 times the rated maximum line-to-ground voltage specified by Table 1 in IEEE Std C57.19.01-2000™. Partial discharge limits are specified in Table 5 of IEEE std C57.19.01-2000™.
- b) Perform a 1 minute dry withstand test at the voltage specified in Table 1 of IEEE Std C57.19.01-2000™. If a flashover occurs outside the insulating envelope, the test may be repeated by restarting the test. If the repeat test also results in a flashover, the bushing shall be considered to have failed. No partial discharge measurements are required at this test level.
- c) Repeat measurements of RIV or apparent charge at 1.5 times rated maximum line-to-ground voltage. Table 5 of IEEE Std C57.19.01-2000™ specifies partial discharge limits.